



1. Use A Sharpie to mark desired location of the FA-TB2A bracket



2. Using a Screw Gun attach hanger bolts to the tree  
Note: You may also use a 7/16" socket wrench and a drill to attach the hanger bolts



3. Place FA-TB2A bracket over hanger bolts and secure with hex nuts



4. Run lead wire through slot & attach fixture to bracket. Use set screw to set desired fixture angle. Secure lead wire to tree and connect to main cable